

### **RANA 215 P**

#### **Product information**

- 1-Anticorrosive primer.
- 2-Excellent water resistance.
- 3- Good erosion.
- 4 -Designed for application directly over steel.
- 5-Fast drying.

#### Physical data

Colour: Orange Finish: Flat Flash point:  $24^{\circ c}$  Volume solids:  $50 \pm 2\%$ 

D.f.t: 50-60 microns Specific gravity:  $1.5 \pm 0.05 \text{gr/cm}^3$  Theoretical coverage:  $10 \text{ m}^2/\text{lit}$  (at 50  $\mu$  d.f.t)

Drying time at 25°c:

touch dry: 30 min dry to handle: 2 hr full cure: 72 hrs

Component: 1

Application methods: Conventional spray or brush or

airless spray or roller

Recoat intervals\*: 10°c 25°c 40°c (mild condition): Min: 6 hrs 2 hrs 1 hrs Max: 24 hrs 10 hrs 6 hrs

Recommended thinner: RANA THINN 26
Recommended cleaner: RANA CLEAN 26

Shelf life: 6 months when stored indoors in unopened

Origin1al containers at 5 to 40°c (cool and dry

place).

Curing mechanism: By solvent release

Substrate: Steel

<sup>\*:</sup> For recoating the surface should be free of dust ,grease and contamination



## RANA 215 P Typical uses

As a primer and rust prevent coat for steel .

other uses are:

Ships hulls, decks and super structures, offshore structures and piping in chemical plants, refineries, bridges and cranes.

#### **Application information**

This RANA CHEM's product is a red lead chlorinated rubber primer for immersion and nonimmersion systems.

To obtain the maximum performance for which this product is formulated, strict adherence to all application, instructions precautions, conditions and limitations is necessary.

### **Application equipment**

The following equipment is listed as a guide and suitable equipment from other manufactures may be used.

Adjustments of pressure and change of tip size may be needed to obtain the proper spray characteristics.

1-Airless spray: standard airless spray equipment having
A 28:1 or higher pump ratio and a fluid tip with a 0.457 to 0.660 mm orifice.

2-Conventional spray:Industrial equipment with suitable aircap having a fluid tip with A 2- 2.2 mm orifice . 3-Brush/roller.

4- Mixer



### **RANA 215 P**

#### Caution

- 1-Keep away from heat and open flame.
- 2-Keep containers closed.
- 3-Use with adequate ventilation.
- 4-Avoid prolonged and repeated contact with skin.
- 5-Use fresh air masks and explosion proof equipment.
- 6-Take precautionary measures against static discharges.

### **Application procedure**

- 1-Flush equipment with recommended cleaner before use.
- 2-Stir all material thoroughly before applying.
- 3-Thinning with thinner as needed for workability.
- 4- Apply a wet coat by even, parallel passes.overlap each pass 50% to avoid bare areas, pinholes or holidays.

Small damaged or bare areas and random pinholes or

holidays can be repaired by simply applying additional material.

5-In confined areas ventilate with clean air during application and drying until all solvents are removed.

Temperature and humidity of ventilating air must be such that moisture condensation will not form on surface.

6-Clean all equipment with recommended cleaner immediately after use.

### **Environmental condition**

Environmental temperature must be 10-40°c.

Surface temperature must be at least 3°c above dew point to prevent condensation. At freezing temperature surface must be free of ice and relative humidity below 80 %.



### **RANA 215 P**

### **Surface preparation**

Sand blasting or wire brushing to a standard of St2 (Sa 2.5 - Sa3, SIS 055900, ISO 8501-1).